EPA Notification of Hazardous Waste Site

United States Environmental Prote Washington DC 2046.

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compen- paper. Indicate the letter of the item sation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of which applies.

173

A	Description of the North									
4	Person Required to Notify: Enter the name and address of the person		Name	Ford M	Notor Com	pany				
	or organization required to notify.		Street	966 Sc	outh Miss	issippi	River I	Blvd.		
			City	St. Pa	ul		State	MN	Zip Code	55116
В	Site Location:					٥.				
Enter the common name (if known) and actual location of the site.		Name of Site Ford Motor Co Steam Plant Street 966 South Mississippi River Blvd.								
			Street	900 30	outh Miss	15S1pp1	River	siva.		
			City	St. Pa	aul County	Ramsey	State	MN	Zip Code	55116
C	Person to Contact: Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.		No O E	a and Tistal	Suss	sman. V.	H. Dir	ector		
			Name (Last, First and Title) Sussman, V.H., Director Stationary Source Environ							
			Phone	(313)	323-2896				Control	
D	Dates of Waste Handling:							110.55		
	Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site		From (Voor)	Unknow	n To (Year)	1	966	US EP	A RECORDS C	ENTER REGION :
			From (rear)	Onknow	10 (rear)			111111		
								1111111	4844	
									4044	16
E	Waste Type: Choose the option	you pr	efer to comp	lete						
					Ontion 2	. This anti-	n in avail	abla to s	orcone for	ailine much sh
Option I: Select general waste types and so you do not know the general waste types or encouraged to describe the site in Item I—I			sources, you	are	Resource		ion and R	ecovery		Section 30
	General Type of Waste: Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category. Source of Place and boxes.		of Waste		Specific	Type of W	aste:			
			X in the appro	opriate	EPA has	assigned a	four-digit	numbe	to each h	azardous wa
					appropria	the regulat	it number	in the t	n 3001 of h	RCRA. Enter ded A copy
					the list of	f hazardou	s wastes a	and code	es can be o	btained by
					located.	g the EPA	Region se	rving th	e State in i	which the si
	1. Drganics	1. □ M	ining							
	2. D Inorganics		nstruction	TO M						
	3. D Solvents	3. □ Te								
	4. ☐ Pesticides	4. □ Fe								
	5. ☐ Heavy metals		per/Printing						100	
	6. □ Acids		ather Tanning							
8	7 🗆 Bases		on/Steel Foun		The same of					
	B. D PCBs		nemical, Gene							
	9. Mixed Municipal Waste		ating/Polishin							
			☐ Military/Ammunition		P. L.					
			ectrical Condu	ictors						
			Transformers					Series.	V LONE	
			tility Companie							
			anitary/Refuse	9						
		notofinish								

16. ☐ Lab/Hospital 17. Unknown 18. Dother (Specify)

Automotive Manufacturing and Finishing

	Notification of Hazardous Waste Site	Side Two	_					
	Weste Quantity:	Facility Type	Total Facility Waste	Amount				
4	Place an X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space	1. Piles	cubic feet Unknow	gallons				
		2. □ Land Treatment 3. Ⅺ Lendfill	gallons					
	give the estimated combined quantity (volume) of hazardous wastes at the site	4. 🗆 Tanks	Total Facility Area					
<u>.</u>	using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities	5. Impoundment 6. Underground Injection	square feet	:				
		7. Drums, Above Ground	ecres 4.0	· · · · · · · · · · · · · · · · · · ·				
	occupy using square feet or acres.	8. Drums, Below Ground 9. Other (Specify)	·					
	Known, Suspected or Likely Releases t		,					
	Place an X in the appropriate boxes to indicat or likely releases of wastes to the environment	te any known, suspected,	☐ Known 🏗 Suspecte	ed 🗆 Likely 🖽 None				
	Note: Items Hand I are optional. Completing hazardous waste sites. Although completing	these items will assist EPA and State the items is not required, you are end	and local governments in couraged to do so.	locating and assessing				
į	Sketch Map of Site Location: (Options	11)						
	Sketch a map showing streets, highways, routes or other prominent landmarks near							
	the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a	See attached.						
	publishing map showing the site location.			•				
		•	·					
		•						
		,						
		·						
	·	·		· · · · · · · · · · · · · · · · · · ·				
	Description of Site: (Optional)							
	Describe the history and present conditions of the site. Give directions to			·.				
	the site and describe any nearby wells, springs, lakes, or housing, include such							
	information as how waste was disposed and where the waste came from. Provide	•						
	any other information or comments which may help describe the site conditions.							
	Unknown quantities of excavated partially burned wastes which consisted of congealed paint from spray booths, solvents and cleaners were disposed of in this area in 1962 and 1966. The							
	from spray booths, solvents and cleaners were disposed of in this area in 1902 and 1900. The site is a natural low land adjacent to the Mississippi River. The area is approximately 500							
	feet from the river bank.							
	Revision Dated August 1, 1983 During wastewater treatment plant construction during the summer of 1983, another smaller fil							
	area was discovered in vicinity of the steam plant located near the Mississippi River. This							
	area was excavated in July 1983, and all observed paint sludge removed to a secure hazardous waste landfill for off-site disposal. It is believed that the waste paint sludge encountered							
	in this area was the result of	an isolated disposal incide	nt which occurred i	in 1966.				
	Signature and Title:		·	 				
	The person or authorized representative	Name Robert M. Major, P	lant Manager	□ Owner, Present				
	ission as plant managers, superintendents, rustees or attorneys) of persons required to notify must sign the form and provide a	Street 966 South Mississi	ppi River Blvd.	□ Owner, Past				
	mailing address (if different than address in item A). For other persons providing	C+ Davil	MN 55116	☐ Transporter 【☐ Operator, Present				
	notification, the signature is optional. Check the boxes which best describe the	City St. Paul State	I III Zib Code 22110	Operator, Past				
	relationship to the site of the person required to notify. If you are not required	Signature	Date 8/1/83	Other Other				
	to notify check "Other".			. /				

Ξ

REGEIVED

AUG 23 1983



Automotive Assembly Division Ford Motor Company

August 16, 1983

Twin Cities Assembly Plant 986 South Mississippi River Blvd. St. Paul, Minnesota 55116

U. S. Environmental Protection Agency Region V Sites Notification Chicago, IL 60604

Subject: Revision to EPA Notification of Hazardous Waste Site

Ford Twin Cities Assembly Plant

Gentlemen:

Attached is a revised Notification of Hazardous Waste Site form and partial property plan amending our previously revised form T-58, dated October 13, 1983, submitted as required under provisions of Superfund.

Please be advised that the previously submitted form T-58 should be substituted with the attached pages, which have been revised to include another smaller fill area in which waste paint sludge was discovered during ongoing wastewater treatment plant construction.

The enclosed drawing shows the location of this new area. In conjunction with construction in vicinity of the steam plant, the highlighted inactive fill area has been excavated and all observed paint sludge removed to a secure hazardous waste landfill for off-site disposal.

Yours truly,

R. M. Major Plant Manager

nm

Attachment

cc: Mr. D. Day

Minnesota Pollution Control Agency



8/24/83

ATTACHED IS A DUPLICATE COPY OF OUR LETTER OF AUGUST 16. THE ATTACHMENT HAS NOW BEEN SIGNED.

RMM





AUG 3 1 1983

Automotive Assembly Division Ford Motor Company

August 16, 1983

Twin Cities Assembly Plant 966 South MississIppi River Blvd. St. Paul, Minnesota 55116

U. S. Environmental Protection Agency Region V Sites Notification Chicago, IL 60604

Subject: Revision to EPA Notification of Hazardous Waste Site

Ford Twin Cities Assembly Plant

Gentlemen:

Attached is a revised Notification of Hazardous Waste Site form and partial property plan amending our previously revised form T-58, dated October 13, 1983, submitted as required under provisions of Superfund.

Please be advised that the previously submitted form T-58 should be substituted with the attached pages, which have been revised to include another smaller fill area in which waste paint sludge was discovered during ongoing wastewater treatment plant construction.

The enclosed drawing shows the location of this new area. In conjunction with construction in vicinity of the steam plant, the highlighted inactive fill area has been excavated and all observed paint sludge removed to a saure hazardous waste landfill for off-site disposal.

Yours truly,

R. M. Major

Plant Manager

nm

Attachment

cc: Mr. D. Day

Minnesota Pollution Control Agency

	Place an X in the appropriate boxes to find cate the facility types found at the	1. Piles	cubic feet Unkno	nwo.		
	In the "total facility waste amount" space	2. Land Treatment 3. Landfill	gallons			
-	give the estimated combined quantity (volume) of hazardous wastes at the site using cubic fee: or gallons: In the "total facility area" space, give the	4. Tanks Timpoundment	Total Facility Area			
		6. Underground Injection	<u> </u>	<u> </u>		
	estimated area size which the facilities occupy using square feet or acres.	7. Drums, Above Ground 8. Drums, Below Ground 9. Other (Specify)	acres 4.0			
_	Known, Suspected or Likely Releases t					
	Place an X'in the appropriate boxes to indicate or likely releases of wastes to the environment	e any known, suspected,	☐ Known Ø Suspec	ted 🗖 Likely 🗖 No		
	Note: Items Hand I are optional. Completing	these items will assist EPA and State the items is not required, you are en	and local governments in	n locating and assess		
. <u>-</u>	Sketch Map of Site Location: (Optiona		·····	· · · · · · · · · · · · · · · · · · ·		
	Sketch a map showing streets, highways, toutes or other prominent landmarks near the site Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.		See attached.	•		
			·			
				.		
	·					
			·			
			·			
	· .		•			
_				· <u> </u>		
_	Description of Site: (Optional)			, .		
	Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing, include such information as how waste was disposed and where the waste came from Provide any other information or comments which may help describe the site conditions. Unknown quantities of excavated from spray booths, solvents and site is a natural low land adjacent from the river bank.	cleaners were disposed of	in this area in 19	162 and 1966. T		
	Revision Dated August 1, 1983 During wastewater treatment planarea was discovered in vicinity area was excavated in July 1983 waste landfill for off-site distinction area was the result of	of the steam plant located, and all observed paint sl posal. It is believed that	near the Mississi udge removed to a the waste paint s	ippi River. Thi secure hazardou ludge encounter		
	Signature and Title:	But a se se s	Y			
(The person or authorized representative. (such as plant managers, superintendents, rustees or attorneys) of persons required. The person of authorized representative.	Name Robert M. Major, F Street 966 South Mississi		□ Owner, Presen□ Owner, Past□ Transporter		
	mailing address (it different than address in item A). For other persons providing natification, the signature is optional. Check the boxes which best describe the relationship to the site of the person.	City St. Paul Star	MN Zap Code 55116	☼ Operator, Pres— ☐ Operator, Past☐ Other		
	required to notify. If you are not required	Signature	Date 8/1/83	_		

3	TA Wouldan		Пагагион	VVasic Ji	le :	Environmental Protes Agents Washington DC 2046
<u> </u>	This initial notification information required by Section 103(c) of the hensive Environmental Response sation, and Liability Act of 1980 be mailed by June 9, 1981.	Compre- , Compen-	Please type or print additional space, use paper. Indicate the le which applies.	vvos g.c ociis		
<u> </u>	· · · · · · · · · · · · · · · · · · ·				·	<u></u>
Ä	Person Required to Notify:		Ford	Motor Company		•
	Enter the name and address of the person or organization required to notify.					
			Street 966	<u> </u>		
			city St.	PauT	State MN	z: c-se 5 <u>5</u> 116
B	Site Location:				<u></u>	
	Enter the common name (if known) and actual location of the site.		Name of Site Ford	<u> Motor Co St</u>	team Plant	<u></u>
			Street 966	· ·		
			Giv St.	Paul County Rams	sey State MN	Zip Coor 55116
C	Person to Contact:					
•	Enter the name, title (if applicable	e), and	Name (Last, First and Title	Sussman,	V.H., Directo	
	business telephone number of the to contact regarding information	e person	Phone (313)	323-2896		ary Source Environ- Control Office
	submitted on this form.					*
		<u> </u>				
D	Dates of Waste Handling:					
	Enter the years that you estimate treatment, storage, or disposal be ended at the site.	egan and	From (Year) Unkno	Will To (Year)	1966	
			~.		•	
-	Wasaa Taraa Chaasa shaasa			· · · · · · · · · · · · · · · · · · ·	···	
E	Waste Type: Choose the option of Select general waste typou do not know the general waste noouraged to describe the site in	pes and so	ource categories. If sources, you are		ryation and Recover	persons familiar with the Act (RCRA) Section 30
	General Type of Waste: Place an X in the appropriate boxes: The categories listed overlap. Check each applicable category:	Source of Waste: Place an X in the appropri boxes.		listed in the reg appropriate four the list of hazar contacting the E	ed a four-digit numb ulations under Secti r-digit number in the dous wastes and co	per to each hazardous within 3001 of RCRA. Enter boxes provided. A copy desican be obtained by the State in which the s
	1. 🗓 Organics	t. 🗅 Mi	ning.	located.		•
	2. D Inorganics:		nstruction			
	3. D Solvents 4. D Pesticides	3. 🗆 Textiles. 4. 🗆 Fertilizer				
	5. Heavy metals	5. Paper/Printing				
	6. 🗆 Acids	6. 🗆 Leather Tanning				
	7 🗆 Bases		n/Steel Foundry			<u> </u>
	Ş ⊆ PÉBs		emical, General			
	9. Mixed Municipal Waste:	9. □ Plating/Polishing 10. □ Military/Ammunition				
	11. X Other (Specify)		ectrical Conductors			_
			ensformers:	<u> </u>	J	
			ility Companies	1 '		
			initary/Refuse		•	
	•	· · ·	otofinish			<i>:</i>
	•	•	b/Hospital			•
		17. 🗆 Ur	nknown her (Specify)			•
		<u>Automot</u>	ner(specily) <u>:ive Manufactu</u> r- Finishing		÷.	
	Form Approved	ing and	i i i i i i i i i i i i i i i i i i i			· •